

LEATHERMARKET

JMB

Symington House

(Submitted by: John-Paul Eaton on 16 Oct 2014 at 11:27)

External Cleaning SE1 4AA: Graffiti

Score: 6

External Cleaning SE1 4AA: Gym Area

Score: 6

Supporting Photos:

(click on thumbnail to see larger photo)



Internal Cleaning SE1 4AA: Handrails

Score: 3

Comments: *Accumulation of dust on top ledge of panel*

External Cleaning SE1 4AA: Hard Surfaces

Score: 5

External Cleaning SE1 4AA: Road Ways

Score: 5

Grounds Maintenance SE1 4AA: Grassed Areas

Score: 6

Grounds Maintenance SE1 4AA: Planters

Score: 5

Grounds Maintenance SE1 4AA: Shrubs

Score: 5

Internal Cleaning SE1 4AA: Entrance Lobby

Score: 5

Internal Cleaning SE1 4AA: Glazing

Score: 4

Internal Cleaning SE1 4AA: Graffiti

Score: 6

Internal Cleaning SE1 4AA: Lift (Left)

Score: **C**

Internal Cleaning SE1 4AA: Lift (Right)

Score: **C**

Internal Cleaning SE1 4AA: Skirting

Score: **5**

Internal Cleaning SE1 4AA: Lift Lobbies

Score: **C**

Internal Cleaning SE1 4AA: Stairs

Score: **5**

Internal Cleaning SE1 4AA: Stairwell Landings

Score: **5**

Internal Cleaning SE1 4AA: Walls

Score: **5**

Internal Cleaning SE1 4AA: Ledges

Score: **4**

External Cleaning SE1 4AA: Bin Area

Score: **5**

External Cleaning SE1 4AA: Bulk Refuse

Score: **6**

External Cleaning SE1 4AA: Garage Area

Score: **6**

External Cleaning SE1 4AA: Grassed Area

Score: **6**

Grounds Maintenance SE1 4AA: Beds

Score: **4**

Average Scores:
Cleaning 5.1
Grounds 5.0